


Item # 1056701 – Performance Steel Goal

Part List

- 1 – (A) Left Three Way Corner Connector
- 1 – (B) Right Three Way Corner Connector
- 1 – (J) Top Crossbar w Bauer Logos
- 1 – (D) Left Top Shelf Corner Bar
- 1 – (K) Right Top Shelf Corner Bar
- 1 – (H) Top T Connector
- 2 – (C) Uprights
- 1 – (E) Left Side Bar
- 1 – (E) Right Side Bar
- 2 – (F) Bottom Back Bars
- 1 – (I) Bottom T Connector
- 1 – (G) Back Support Bar
- 1 – Net



Assembly Instructions:

Assemble goal frame per the diagram above. Put the net aside for now as attaching the net will be the last step. Part (H) should angle correctly so it can be connected to part (I) as shown.

Once frame is assembled, position the net onto the frame with the 2 red tabs positioned over the top 2 elbows. Make sure the net goes over the top shelf (parts D and K). Then use the string to lace the net onto the front frame. The string goes through the hole in the net and then is threaded through the hole on the welded bar on the back of the pole then goes through the adjacent hole in the net and adjacent hole on the welded bar. Continue to lace until the net is fully attached to the frame with the string. Then tie the string off when you reach your starting point and trim any excess string. Make sure your net is tight the entire time. (note: the net will be laced across the front frame which consists of parts A, J, B, C, E and F)

BAUER